

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re. G.O. Ms. 20/70/PWD Dt. 23-01-1970)

No: 2081870-2025

Name of the School

NAVATEEVAN BETHANY VIDYALAYA

1. Name of the Officer

Lakshmi J. N

2. Location

Nalanchira Thiruvananthapuram North

3. Period for which the certificate is issued

2025-2026

4. Types of building

82.90 x 10.04 x 3.65

5. Nature of defect if any

10.50 x 74.50 x 3.65

9.20 x 8.35 x 3.65

25.10 x 19.15 x 3.65

3 Floors

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks if any)

NIL

6. Any Major defects notices which will render the building unsafe in any manner

NIL

7. Whether maintenance works have been done properly

Yes

8. Whether the structure is sound or not for conducting classes

Yes, Sounds fit for conducting classes under normal wind and weather conditions

Note: 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 05/06/2025

and found to be fit / unfit to conduct classes for the period 2025-2026

for the reason stated above.

Place: Thiruvananthapuram

Date: 05/06/2025



Assistant Engineer

NAVATEEVAN BETHANY VIDYALAYA (CBSE)
BETHANY JUNCTION, NALANCHIRA
THIRUVANANTHAPURAM - 15

